

**TOWN OF NEW WINDSOR
ENGINEER'S OFFICE**

MEMO

TO: PHILIP CROTTY, ATTORNEY FOR THE TOWN

FROM: RICHARD D. MC GOEY, P.E.,
ENGINEER FOR THE TOWN

DATE: JUNE 4, 2002

SUBJECT: HARP ESTATES (COVINGTON ESTATES) RT. 300 – EXTENSION OF
WATER DISTRICT #5

Dear Phil:

We are in receipt of a revised engineering report dated 22 May 2002. Be advised that the revised report does not address all of the issues discussed in the memo to our office of 14 May 2002. Specifically, the engineering report does not demonstrate that the existing water distribution system can adequately provide fire flows and pressures to the water district extension.

Further, be advised that the Fire Inspector's Report dated 21 May 2002, which is Appendix D to the engineering report for the extension of Water District #5, states that fire flows in this area may be a problem.

In addition to the above, we have recently been informed by Camo Pollution Control that the booster pumping station located on Union Avenue, which serves Water District #5, is not capable of meeting existing average daily demands, therefore, a major improvement to this pump station will be required.

On the basis of the above, we cannot recommend an extension of Water District #5 to serve the Harp Estates (Covington Estates) at this time.

RDM:mlm

cc: Mark J. Edsall, P.E. – P.B. Engineer
John Egitto - Camo